

TECHNICIAN KITCHEN

Bulletin# 3-28

6R80

Solenoid E Resistance Change & Code P0770

Technical Bulletin:

Change in **SSE** Resistance for 6R80 Units Manufactured after November 3, 2010

Please be advised that there has been a change in the SSE resistance for units manufactured after November 3, 2010. Prior to this date, units had an SSE resistance of approximately 10.5 ohms. However, for units manufactured after this date, the SSE resistance has been increased to 18 ohms.

It is important to note that this change will impact the transmission performance and possibly set a DTC's. With this solenoid please ensure that any replacements made is using the appropriate SSE resistance based on the date of manufacture.

Solenoid E: Date and OHM's	
Prior November 3 rd 2010	10.5 OHM's
After November 3 rd 2010	18 OHM's

